



WHQS Report - 02/01/2019

WHQS Overall Status



WHQS Result	Properties
PASS	2694
ACCEPT_FAIL	2646

WHQS Elements



Result	BackDoor	Bathroom	FrontDoor	Garden	Heating	Kitchen	Rewire	Roof	SAP
PASS	5333	5128	5333	5329	5307	4638	5289	5333	3230
ACCEPT_FAIL		205		4	27	695	44		2103

Smoke	Windows
5235	5333
98	