## Site photographs taken 30<sup>th</sup> August 2017 – Bridleway 6 Llanbrynmair

Location 1 – Looking southwest towards property at Barlings Barn



 $\label{location 2-Locking Southwest, from boundary between Barlings Barn and Cwm-y-Ffynnon$ 



Location 3 – Looking northeast towards Cwm-y-Ffynnon farmyard, from boundary between Barlings Barn and Cwm-y-Ffynnon




 $\label{location 4-Locking Southwest from Cwm-y-Ffynnon towards boundary with Barlings Barn$ 






Location 5 – Looking southwest towards Cwm-y-Ffynnon farmyard















Location 10 – Looking northeast; bridleway runs across fence line, between two rows of trees












Location 13 – Looking northeast up slope, towards current access track

Location 14 – Looking southwest from above corner of current access track








Location 16 – Looking southwest; bridleway runs along track from gate at location 15, beside boundary between Ffridd Caeaugleision and Ffridd Esgair Gelynen.







Location 18 – Detail of old wall between Ffridd Caeaugleision and Ffridd Esgair Gelynen



Location 19 – Looking southwest back along defined sunken track, from boundary between Ffridd Caeaugleision and Llechwedd Du



Location 20 – Looking northeast across Llechwedd Du, from boundary with Ffridd Caeaugleision



Location 21 – Looking northeast across Llechwedd Du; old boundary wall apparent. Bridleway runs immediately to the right of this wall at this point.



Location 22 - Looking northeast, from point where bridleway crosses stream



Location 23 - Looking northeast across Llechwedd Du



Location 24 – Looking southwest, from a point near boundary between Llechwedd Du and Pant ar Ty



Location 25 – Looking northeast, towards boundary between Llechwedd Du and Pant ar Ty



Location 26 - Looking northeast, towards current access track to Cwm Pen Llydan

